

Operating Manual

Pocket Diamond Scales

CS Series



CALIBRATION OF 10g/0.001g

1. ELECTRONIC POCKET SCALE 1. Under power off condition, press "TARE" switch till the scale displays the ISN (Internal Statement Number).
2. Press "TARE" again, then it displays "0.000g".
3. Put a standard weight of "5g" on the scale.
4. Press "TARE" after the digital display is stable. Then it displays "0.000g".
5. Take the 5g weight away till it displays "0.000g". Then put a 10g weight on the center of weighing area.
6. Press "TARE" after the digital display is stable. Then it displays "10.000g".
7. Press "TARE" till power off.
8. Press "ON/OFF". Then test the scale is accurate or not. If not, repeat the process.

Regards

